


SECOND EDITION

# WELDING ENGINEERING

## AN INTRODUCTION

DAVID H. PHILLIPS



WILEY

# **Welding Engineering**

An Introduction

*David H. Phillips*  
*The Ohio State University*  
*OH, USA*

Second Edition

**WILEY**

## Contents

	<b>Preface</b>	<i>xiii</i>
	<b>About the Companion Website</b>	<i>xv</i>
<b>1</b>	<b>What Is Welding Engineering?</b>	<b>1</b>
1.1	Introduction to Welding Processes	1
<b>2</b>	<b>Arc Welding Processes</b>	<b>3</b>
2.1	Fundamentals and Principles of Arc Welding	3
2.1.1	Fundamentals of an Electric Arc	5
2.1.2	Arc Voltage	6
2.1.3	Polarity	7
2.1.4	Heat Input	9
2.1.5	Welding Position	10
2.1.6	Filler Metals and Electrodes	11
2.1.7	Shielding	11
2.1.7.1	Gas Shielding	11
2.1.7.2	Flux Shielding	12
2.1.8	Weld Joints and Weld Types for Arc Welding	13
2.1.9	Primary Operating Variables in Arc Welding	14
2.1.9.1	Voltage	14
2.1.9.2	Current	14
2.1.9.3	Electrode Feed Rate/Wire Feed Speed	15
2.1.9.4	Welding Travel Speed	15
2.1.10	Metal Transfer Mode	16
2.1.11	Arc Blow	16
2.1.12	Common Arc Welding Defects and Discontinuities	17
2.2	Arc Welding Power Supplies	17
2.2.1	Transformers	18
2.2.2	Generators	18
2.2.3	Important Electrical Elements in Arc Welding Power Supplies	20
2.2.4	Volt-Ampere Characteristic of Arc Welding Power Supplies	23
2.2.5	Duty Cycle	26
2.2.6	Modern Advanced Arc Welding Power Supplies	27
2.3	Shielded Metal Arc Welding	30

- 2.4 Gas Tungsten Arc **Welding** 36
- 2.5 Plasma Arc **Welding** 44
- 2.6 Gas Metal Arc **Welding** 47
- 2.7 Flux Cored Arc **Welding** 55
- 2.8 Submerged Arc **Welding** 58
- 2.9 Other Arc **Welding** Processes 63
  - 2.9.1 Electro~~gas~~ **Welding** 63
  - 2.9.2 Electroslag **Welding** 63
  - 2.9.3 Arc Stud **Welding** 65
  - 2.10 Test Your **Knowledge** 68
  
- 3 Resistance **Welding** Processes 69**
  - 3.1 Fundamentals and Principles of Resistance **Welding** Processes 69
    - 3.1.1 Resistance and **Resistivity** 69
    - 3.1.2 Current Range and Lobe Curves 72
    - 3.1.3 Modern **Equipment** and Power Supplies 74
  - 3.2 Resistance Spot **Welding** 75
  - 3.3 Resistance Seam **Welding** 79
  - 3.4 Resistance **Projection** **Welding** 81
  - 3.5 High Frequency **Welding** 83
  - 3.6 Flash **Welding** 85
  - 3.7 Test Your **Knowledge** 88
  
- 4 Solid-State **Welding** Processes 91**
  - 4.1 Fundamentals and Principles of Solid-State **Welding** 91
    - 4.1.1 Solid-State **Welding** Theory 91
    - 4.1.2 Roll Bonding Theory 92
  - 4.2 Friction **Welding** Processes 93
    - 4.2.1 Inertia Friction **Welding** 94
    - 4.2.2 Continuous Drive Friction **Welding** 96
    - 4.2.3 Linear Friction **Welding** 97
    - 4.2.4 Friction Stir **Welding** 98
  - 4.3 Other Solid-State **Welding** Processes 101
    - 4.3.1 Diffusion **Welding** 101
    - 4.3.2 Explosion **Welding** 104
    - 4.3.3 Ultrasonic **Welding** 106
  - 4.4 Test Your **Knowledge** 110
  
- 5 High-Energy Density **Welding** Processes 111**
  - 5.1 Fundamentals and Principles of High-Energy Density **Welding** 111
    - 5.1.1 Power Density 111
    - 5.1.2 Keyhole Mode **Welding** 113
  - 5.2 Laser Beam **Welding** 113
  - 5.3 Electron Beam **Welding** 116
  - 5.4 Test Your **Knowledge** 118

<b>6</b>	<b>Other Approaches to Welding and Joining</b>	<b>121</b>
6.1	Brazing and Soldering	121
6.2	Welding of Plastics	123
6.2.1	Hot Tool (Plate) Welding	124
6.2.2	Hot Gas Welding	125
6.2.3	Implant Induction Welding	126
6.2.4	Ultrasonic Welding	126
6.2.5	Vibration Welding	127
6.3	Adhesive Bonding	128
6.4	Novel and Hybrid Welding Processes	128
6.5	Additive Manufacturing	131
6.6	Oxyfuel Welding and Cutting	132
6.7	Other Cutting Processes	137
6.7.1	Plasma Cutting	137
6.7.2	Laser Beam Cutting	138
6.7.3	Air Carbon Arc Gouging	138
6.8	Test Your Knowledge	140
<b>7</b>	<b>Design Considerations for Welding</b>	<b>141</b>
7.1	Introduction to Welding Design	141
7.2	Mechanical Properties	141
7.2.1	Yield Strength	141
7.2.2	Tensile Strength	142
7.2.3	Ductility	142
7.2.4	Fatigue Strength	142
7.2.5	Toughness	142
7.2.6	Mechanical Properties—Effect of Temperature	144
7.3	Physical Properties	144
7.3.1	Thermal Conductivity	144
7.3.2	Melting Temperature	144
7.3.3	Coefficient of Thermal Expansion	145
7.3.4	Electrical Conductivity	145
7.4	Design Elements for Welded Connections	145
7.4.1	Joint and Weld Types	145
7.4.2	Joint and Weld Type Selection Considerations	148
7.4.3	Weld Joint Nomenclature—Groove Welds	150
7.4.4	Weld Joint Nomenclature—Fillet Welds	151
7.4.5	Welding Positions	151
7.5	Welding Symbols	154
7.6	Weld Sizing	159
7.7	Computational Modeling of Welds	162
7.8	Test Your Knowledge	164
<b>8</b>	<b>Heat Flow, Residual Stress, and Distortion</b>	<b>165</b>
8.1	Heat Flow	165
8.2	Fundamentals and Principles of Residual Stress and Distortion	169

- 8.3 Approaches to Minimizing or Eliminating Distortion 172
- 8.4 Test Your Knowledge 176
- 9 Welding Metallurgy 177**
- 9.1 Introduction to Welding Metallurgy 177
- 9.2 The Fusion Zone 179
- 9.3 The Partially Melted Zone 180
- 9.4 The Heat-Affected Zone (HAZ) 182
- 9.5 Introduction to Phase Diagrams 183
- 9.6 Test Your Knowledge 186
- 10 Welding Metallurgy of Carbon Steels 187**
- 10.1 Introduction to Steels 187
- 10.2 Steel Microstructures and the Iron-Iron Carbide Diagram 189
- 10.3 Continuous Cooling Transformation (CCT) Diagrams 193
- 10.4 Hardness and Hardenability 196
- 10.5 Hydrogen Cracking 198
- 10.6 Heat-Affected Zone Microstructures in Steel 200
- 10.7 Advanced High-Strength Steels 202
- 10.8 Test Your Knowledge 204
- 11 Welding Metallurgy of Stainless Steels 207**
- 11.1 Introduction to Stainless Steels 207
- 11.2 Constitution Diagrams 208
- 11.3 Martensitic Stainless Steels 210
- 11.4 Ferritic Stainless Steels 211
- 11.5 Austenitic Stainless Steels 214
- 11.6 Duplex Stainless Steels 218
- 11.7 Precipitation-Hardening Stainless Steels 220
- 11.8 Test Your Knowledge 220
- 12 Welding Metallurgy of Nonferrous Alloys 223**
- 12.1 Aluminum Alloys 223
- 12.2 Nickel-Based Alloys 227
- 12.3 Titanium Alloys 231
- 12.4 Copper Alloys 234
- 12.5 Magnesium Alloys 235
- 12.6 Test Your Knowledge 237
- 13 Weld Quality 239**
- 13.1 Weld Discontinuities and Defects 239
- 13.2 Mechanical Testing of Weldments 240
- 13.2.1 Tensile Testing 240
- 13.2.2 Ductility Testing 241
- 13.2.3 Toughness Testing 243
- 13.2.4 Fatigue Testing 244

<b>13.3</b>	<b>Nondestructive Testing</b>	<b>248</b>
13.3.1	Visual Examination	249
13.3.2	Liquid Penetrant Testing	249
13.3.3	Magnetic Particle Testing	250
13.3.4	Radiographic Testing	252
13.3.5	Ultrasonic Testing	254
<b>13.4</b>	<b>Introduction to Fractography</b>	<b>255</b>
<b>13.5</b>	<b>Test Your Knowledge</b>	<b>258</b>
<b>14</b>	<b>Codes, Standards, and Welding Qualification</b>	<b>259</b>
14.1	Introduction to Standards	259
14.2	AWS D1.1—"Structural Welding Code—Steel"	265
14.2.1	Welding and Welder Qualification	265
14.2.2	Fabrication and Inspection	272
14.3	Test Your Knowledge	272
<b>15</b>	<b>Safe Practices in Welding</b>	<b>275</b>
15.1	Electrical Shock	275
15.2	Radiation	275
15.3	Burns	275
15.4	Smoke and Fumes	276
15.5	Welding in Confined Space	276
15.6	Fire and Explosion Danger	276
15.7	Compressed Gasses	276
15.8	Hazardous Materials	277
15.9	Test Your Knowledge	277
	<b>Index</b>	<b>279</b>

## Index

### **a**

AC 39  
 Additive manufacturing 131–132  
 Adhesive bonding 128  
 Advanced arc welding power supplies 27–29  
 Advanced High-Strength Steels 202–204  
 Air Carbon Arc Gouging 138  
 AISC 262–263  
 AISI steel classification 187–188  
 Allotropic behavior of iron 188  
 Aluminum alloys 223–227  
 ANSI Z49.1 275, 277  
 API 262  
 Arc 5–6  
 Arc blow 16–17  
 Arc efficiency 10  
 Arc length 31–32  
 Arc Stud Welding 65  
 Arc voltage 6–7  
 Arc welding processes 3–68  
   arc stud welding 65  
   electrogas welding 63  
   electroslag welding 63  
   flux cored arc welding 55–58  
   gas metal arc welding 47–55  
   gas tungsten arc welding 36–43  
   plasma arc welding 44–47  
   shielded metal arc welding 30–36  
   submerged arc welding 58–63  
 Arc welding defects 17  
 Arc welding operating variables 14–16  
 Arc welding power supplies 17–29  
 ASME 262–263  
 ASTM steel classification 188

Austenitic stainless steels 214–218  
 AWS 259–264  
 AWS D1.1 265–272

### **b**

Backing bars 147, 149–150  
 Bainite 193  
 Bend testing (*see* Guided Bend Testing)  
 Brazing 121–123  
 Burns 275–275

### **c**

Carbon equivalent (CE) 197–198  
 Cathodic cleaning 37–39  
 CCT diagrams (*see* Continuous Cooling Transformation Diagrams)  
 CE (*see* carbon equivalent)  
 Cementite 189  
 Certified Welding Inspector (CWI) 249  
 Charpy V-Notch Impact Toughness Test 143, 243–244  
 Codes 259–273  
 Coefficient of thermal expansion 145  
 Compressed gasses 276  
 Computational modeling of welds 162–164  
 Conduction 165–166  
 Constant current power supply 23–25  
 Constant voltage power supply 23–26  
 Constitution Diagrams 208–210, 216  
 Continuous Cooling Transformation (CCT) Diagrams 193–196  
 Continuous Drive Friction Welding 96–97  
 Convection 165–166  
 Cooling rate 167–169  
 Contact tip 49



Copper alloys 234–235  
 Current 14  
 Current range curves 72–73

**d**

DCEN 7–9, 39  
 DCEP 7–9, 39  
 Defects 17, 239–240  
 Design considerations for welding 141–164  
 Diffusion Welding 101–104  
 Discontinuities 17, 239–240  
 Distortion 169–176  
 Distortion control 172–176  
 Ductile-to-brittle transition 243–244  
 Ductility 142  
 Ductility testing 241–243  
 Duplex stainless steels 218–220  
 Duty cycle 26–27  
 Dynamic resistance curves 71–72

**e**

Electrical conductivity 145  
 Electrical shock 275  
 Electrode angle 32  
 Electrode extension 48–50  
 Electrode tip angle 39–40  
 Electrode feed rate 15  
 Electrode specification  
   flux cored arc welding 56–57  
   gas metal arc welding 54–55  
   gas tungsten arc welding 41–42  
   shielded metal arc welding 33–35  
   submerged arc welding 59–62  
 Electrodes 11, 76–79  
 Electrogas Welding 63  
 Electron Beam Welding 116–118  
 Electroslag Welding 63  
 Embrittlement (*see* interstitial embrittlement)  
 Explosion Welding 104–106

**f**

Fatigue strength 142  
 Fatigue testing 244–247  
 FCAW (*see* Flux Cored Arc Welding)  
 Fe-Cr binary phase diagram 207–208  
 Ferrite 188–192, 194–195  
 Ferritic stainless steels 211–214

Filler metal specification 41–42  
 Filler metals 11  
 Fillet weld sizing 159–162  
 Fillet welds 151–152  
 Fire and explosion danger 276  
 Fitness-for-service 239  
 Flash Welding 85–88  
 Flux Cored Arc Welding 55–58  
 Flux shielding 12, 52  
 Fractography 255–258  
 Fracture toughness 142–144, 244–245  
 Friction Stir Welding 98–101  
 Friction Welding 93–101  
 Fumes 276  
 Fusion zone 179–180

**g**

Gas Metal Arc Welding 47–55  
 Gas shielding 11  
 Gas Tungsten Arc Welding 36–44  
 Generators 18  
 Globular transfer mode 52–53  
 GMAW (*see* Gas Metal Arc Welding)  
 Groove angle 151  
 Groove welds 151  
 GTAW (*see* Gas Tungsten Arc Welding)  
 Guided Bend Testing 241–242

**h**

Hardenability 196–198  
 Hardness 196–198  
 HAZ (*see* heat-affected zone)  
 HAZ liquation cracking 181–182, 229, 231  
 HAZ softening 183, 224–225  
 Hazardous materials 277  
 Heat-affected zone 182–183, 200–202  
 Heat flow 165–169  
 Heat input 9  
 Heat treating of steels (preheat and postweld) 198  
 High-energy density welding 111–118  
   electron beam welding 116–118  
   laser beam welding 113–116  
 High frequency starting 42–43  
 High Frequency Welding 83–85  
 Hold time 75–76  
 Hot Gas Welding of plastics 125–126

Hot Tool (Plate) Welding of plastics 124–125  
 Hybrid welding 128–129  
 Hydrogen cracking 198–200

## *j*

Implant Induction Welding of plastics 126  
 Incomplete fusion 239–240  
 Incomplete penetration 239–240  
 Inertia Friction Welding 94–96  
 Interstitial embrittlement of titanium 233  
 Inverter power supplies 22  
 Ionization of a gas 5  
 Iron-Iron Carbide Diagram 189–193  
 ISO 259–260

## *j*

Joint and weld types 145–150  
 Joint design 13–14, 32–33, 148–150

## *k*

Keyhole mode welding 44–46, 113

## *l*

Lamellar cracking 240  
 Laser Beam Cutting 138  
 Laser Beam Welding 113–116, 128–132  
 Leg size 151–152  
 Linear Friction Welding 97–98  
 Liquid Penetrant Testing 249–250  
 Lobe Curves 72–74  
 Low hydrogen practice 199

## *m*

Magnesium alloys 235–237  
 Magnetic Particle Testing 250–252  
 Martensite 192–201  
 Martensitic stainless steels 210–211  
 Mechanical properties 141–144  
 Mechanical testing of weldments 240–248  
 Melting temperature 144  
 Metal transfer mode 16, 50–53  
 MIG Welding (*see* Gas Metal Arc Welding)

## *n*

Nickel-based alloys 227–231  
 Nondestructive testing 248–255  
   liquid penetrant 249–250  
   magnetic particle 250–252

  radiographic 252–254  
   ultrasonic 254–255  
   visual 249

Novel and hybrid welding  
   processes 128–131  
   deltaspot 129–130  
   hybrid laser 128–129  
   lightweld 130–131  
   tiptig 129

## *o*

Orbital welding 40–41  
 Overlap 17, 240  
 Oxyfuel Cutting 132–137  
 Oxyfuel Welding 132–137

## *p*

Partially melted zone 180–182  
 PAW (*see* Plasma Arc Welding)  
 Pearlite 190–195  
 Peltier effect 74–75  
 Phase control 21–22  
 Phase diagrams 183–185  
 Physical properties 144–145  
 Pinching effect 52  
 Plasma Arc Welding 44–47  
 Plasma Cutting 137–138  
 Plastics welding 123–128  
   hot gas welding 125–126  
   hot tool (plate) welding 124–125  
   implant induction welding 126  
   ultrasonic welding 126  
   vibration welding 127  
 Polarity 7, 39  
 Polymers 123–127  
 Porosity 17, 225–226, 239–240  
 Power density 111–113  
 Power supplies 17–29  
 Precipitation-hardening stainless steels 220  
 Preheating 198  
 Prequalified welding procedure 265–267  
 Procedure Qualification Record (PQR) 268  
 Projection weld fasteners 82  
 Projection Welding 81–83  
 Proximity effect 84–85  
 Pulsed waveform 29  
 Pulsing 23, 39–41

**q**

Qualification (welding and welder)  
265–272

**r**

Radiation 275  
Radiographic Testing 252–254  
Rectifiers 21–23  
Residual stress 169–172  
Residual stress patterns 171  
Resistance and resistivity 69–72  
Resistance Projection Welding 81–83  
Resistance Seam Welding 79–81  
Resistance Spot Welding 75–79  
Resistance welding 69–88  
    current range curves 72–74  
    electrodes 76–79  
    flash welding 85–88  
    high frequency welding 83–85  
    lobe curves 72–74  
    power supplies 74–75  
    projection welding 81–83  
    seam welding 79–81  
    spot welding 75–79  
Roll Bonding Theory 92–93  
Root gap 149–151

**s**

SAE steel classification 187–188  
Safe practices in welding 275–277  
SAW (*see* Submerged Arc Welding)  
Schaeffler Diagram 208–210  
SCRs 21–22  
Seam Welding 79–81  
Self-regulation 24–25, 48–49  
Sensitization of stainless steels 217–218  
Shielded Metal Arc Welding 30–36  
Shielding 11  
Shielding gas 11, 37, 53  
Short circuit transfer mode 27–29, 52  
Skin effect 83–84  
Slag inclusions 17, 252–253  
SMAW (*see* Shielded Metal Arc Welding)  
Smoke and fumes 276  
S-N Curve 246–247  
Soldering 121–123  
Solidification cracking 215–216, 226–227

Solid-state welding processes 91–110  
    continuous drive friction welding 96–97  
    diffusion welding 101–104  
    explosion welding 104–106  
    friction stir welding 98–101  
    inertia friction welding 94–96  
    linear friction welding 97–98  
    ultrasonic welding 106–109  
Solid-state welding theory 91–93  
Spontaneous bonding 91–92  
Spot Welding 75–79  
Spray transfer mode 51–53  
Squeeze time 75–77  
Stainless steels 207–220  
    austenitic 214–218  
    duplex 218–220  
    ferritic 211–214  
    martensitic 210–211  
    precipitation-hardening (PH) 220  
Standards 259–273  
Steel microstructures 189–193  
Steels 187–204  
Stick Welding (*see* Shielded Metal Arc Welding)  
Stickout 49  
Strain-age cracking 229–231  
Stress-Strain Curve 243  
Structural Welding Code – Steel 265–272  
Submerged Arc Welding 58–63

**t**

Temper bead welding 198–199  
Tempering 193, 195–196, 198  
Tensile strength 142  
Tensile testing 240–241  
Testing of weldments  
    mechanical 240–247  
    nondestructive 248–255  
Thermal conductivity 144  
Three bar analogy 169–170  
TIG Welding (*see* Gas Tungsten Arc Welding)  
Time Temperature Transformation (TTT)  
    Diagrams 193–195  
Tip angles (Gas Tungsten Arc Welding) 39–40  
Titanium alloys 231–234  
Torch angle 54  
Toughness 142  
Toughness testing 243–244

- Transfer mode 16, 50–53
  - Transformers 18
  - Transition current (Gas Metal Arc Welding) 51
  - Travel speed 15–16, 31
  - TTT Diagrams (*see* Time Temperature Transformation Diagrams)
- U**
- Ultrasonic Testing 254–255
  - Ultrasonic Welding of metals 106–110
  - Ultrasonic Welding of plastics 126–127
  - Undercut 17, 240, 246
- V**
- Vibration Welding of plastics 127
  - Visual Examination 249
  - Voltage 14
  - Volt-ampere characteristic 23–26
- W**
- Weld discontinuities and defects 17, 239–240
  - Weld joints 13
  - Weld quality 239–258
  - Weld sizing 159–162
  - Weld types 13
  - Welder Performance Qualification (WPQ) 271
  - Welding codes and standards 259–273
  - Welding Engineering 1
  - Welding in confined space 276
  - Welding metallurgy 177–186
  - Welding metallurgy of carbon steels 187–205
  - Welding metallurgy of nonferrous alloys 223–238
  - Welding metallurgy of stainless steels 207–221
  - Welding positions 151–154
  - Welding power supplies 17–29
  - Welding procedure development 267
  - Welding Procedure Specification (WPS) 270
  - Welding symbols 154–159
  - Welding test plate 269
  - Wire feed speed 15, 50
  - WRC-1992 diagram 216–217
- Y**
- Yield strength 141–142