



Welding and Metal Fabrication

Larry Jeffus

International
Edition

Contents

Projects	xv
Preface	xviii
Features of the Text	xxi
Acknowledgments	xxiii
About the Author	xxiv

CHAPTER 1	Introduction.....	1
	Objectives.....	1
	Key Terms	1
	Introduction	1
	<i>Welding Applications</i>	2
	<i>Fabrication Steps</i>	3
	Welding Defined.....	5
	<i>Weld Quality</i>	5
	Welding and Cutting Processes	6
	<i>Gas Metal Arc Welding</i>	7
	<i>Flux Cored Arc Welding</i>	8
	<i>Shielded Metal Arc Welding</i>	8
	<i>Gas Tungsten Arc Welding</i>	9
	<i>Oxyacetylene Welding, Brazing,</i> <i>and Cutting</i>	10
	Thermal Cutting Processes	10
	<i>Oxyfuel Gas Cutting</i>	10
	<i>Plasma Arc Cutting</i>	10
	Demonstrations, Practices, and Projects	11
	<i>Assembling the Parts</i>	11
	<i>Selection of the Joining Process</i>	12

Occupational Opportunities in Welding... 12	
<i>Metric Units</i>	13
<i>Welding Video Series</i>	15
Review Questions	15

CHAPTER 2	Welding Safety	17
	Objectives.....	17
	Key Terms	17
	Introduction	17
	Burns	18
	<i>First-Degree Burns</i>	18
	<i>Second-Degree Burns</i>	18
	<i>Third-Degree Burns</i>	19
	<i>Burns Caused by Light</i>	19
	Eye and Ear Protection	20
	<i>Face and Eye Protection</i>	20
	<i>Ear Protection</i>	23
	Respiratory Protection.....	23
	Ventilation	26
	<i>Forced Ventilation</i>	26
	Material Specification Data	
	Sheet (MSDS)	27
	Waste Material Disposal	27
	Ladder Safety.....	27
	<i>Types of Ladders</i>	27
	<i>Ladder Inspection</i>	27
	<i>Rules for Ladder Use</i>	28
	Electrical Safety.....	28
	<i>Electrical Safety Systems</i>	30

Voltage Warnings	31	Summary	47
<i>Extension Cords</i>	31	Review Questions	47
<i>Safety Rules for Portable Electric Tools</i>	32	CHAPTER 3 Shop Math	49
General Work Clothing	33	Objectives	49
Special Protective Clothing	33	Key Terms	49
<i>Hand Protection</i>	34	Introduction	49
<i>Body Protection</i>	34	Types of Numbers	50
<i>Waist and Lap Protection</i>	34	General Math Rules	51
<i>Arm Protection</i>	34	Equations and Formulas	51
<i>Leg and Foot Protection</i>	35	Whole Numbers	52
Handling and Storing Cylinders	35	<i>Adding and Subtracting Whole</i>	
<i>Securing Gas Cylinders</i>	35	<i>Numbers</i>	52
<i>Storage Areas</i>	35	<i>Multiply and Divide Whole Numbers</i>	53
<i>Cylinders with Valve Protection Caps</i>	35	Decimal Fractions	54
<i>General Precautions</i>	35	<i>Adding and Subtracting Decimal</i>	
Fire Protection	37	<i>Fractions</i>	54
<i>Fire Watch</i>	37	<i>Multiply and Divide Decimal Fractions</i> ...	54
<i>Fire Extinguishers</i>	37	<i>Rounding Numbers</i>	55
<i>Location of Fire Extinguishers</i>	38	Mixed Units	56
<i>Use</i>	39	<i>Adding and Subtracting Mixed Units</i>	56
Equipment Maintenance	39	<i>Multiply and Divide Mixed Numbers</i>	58
<i>Hoses</i>	40	Fractions	59
Work Area	40	<i>Adding and Subtracting Fractions</i>	59
Hand Tools	40	<i>Multiply and Divide Fractions</i>	60
<i>Hand Tool Safety</i>	41	Converting Numbers	61
<i>Hammer Safety</i>	41	<i>Converting Fractions to Decimals</i>	62
Power Tools	42	<i>Tolerances</i>	62
<i>Grinders</i>	42	<i>Converting Decimals to Fractions</i>	62
<i>Drills</i>	43	<i>Conversion Charts</i>	62
Metal Cutting Machines	44	<i>Measuring</i>	64
<i>Shears and Punches</i>	44	Summary	64
<i>Cut-Off Machines</i>	45	Review Questions	65
<i>Band Saws</i>	45	CHAPTER 4 Reading Technical	
Material Handling	45	Drawings	66
<i>Lifting</i>	45	Objectives	66
<i>Hoists or Cranes</i>	45	Key Terms	66
<i>Hauling</i>	46	Introduction	67

Mechanical Drawings..... 67

Lines 68

Types of Drawings 70

Special Views 72

Dimensioning..... 72

Drawing Scale..... 74

Reading Mechanical Drawings..... 75

Sketching 75

Erasers and Erasing 80

Graph Paper 80

Computers and Drawings 83

Summary 86

Review Questions 86

CHAPTER 5 **Welding Joint Design,
Welding Symbols 87**

Objectives..... 87

Key Terms 87

Weld Joint Design 88

Welding Symbols 95

Indicating Types of Welds 95

Weld Location 96

Location Significance of Arrow 97

Fillet Welds 97

Plug Welds..... 98

Spot Welds..... 99

Seam Welds 100

Groove Welds 101

Backing..... 102

Flange Welds..... 103

Nondestructive Testing Symbols 103

Summary 107

Review Questions 107

CHAPTER 6 **Fabricating Techniques
and Practices 108**

Objectives..... 108

Key Terms 108

Introduction 109

Fabrication..... 109

Safety..... 110

Parts And Pieces 111

Tack Welds..... 111

Location and Alignment Points 113

Overall Tolerance 113

Weld Distortion..... 117

Layout..... 121

Nesting 126

Kerf Space..... 128

Layout Tools..... 130

Material Shapes 131

Assembly 132

Assembly Tools..... 134

Clamps 134

Fixtures..... 135

Fitting..... 136

Summary 137

Review Questions..... 137

CHAPTER 7 **Welding Shop
Practices 139**

Objectives..... 139

Key Terms 139

Introduction 139

Job-Related Skills 140

Time Management..... 140

Teamwork..... 140

Planning and Thinking Ahead 140

Work Ethics..... 141

Conserving Materials and Supplies 141

Metal Conservation 141

Electrode Conservation 142

Gas Conservation 143

Energy Conservation 143

Recycling..... 144

General Shop Practices	144	CHAPTER 9 Shielded Metal Arc	
<i>Operating Equipment</i>	144	Welding Plate.....	165
<i>Hand Signals</i>	144	Objectives.....	165
<i>Outsourcing</i>	146	Key Terms	165
Summary	147	Introduction	165
Review Questions.....	147	Electrodes.....	166
CHAPTER 8 Shielded Metal Arc		<i>F3 E6010 and E6011 Electrodes</i>	166
Equipment, Setup,		<i>F2 E6012 and E6013 Electrodes</i>	166
and Operation.....	148	<i>F4 E7016 and E7018 Electrodes</i>	166
Objectives.....	148	<i>Effect of Too High or Too Low</i>	
Key Terms	148	<i>Current Settings</i>	166
Introduction	148	<i>Electrode Size and Heat</i>	167
Welding Current.....	149	<i>Arc Length</i>	168
<i>Electrical Measurement</i>	149	<i>Electrode Angle</i>	169
<i>SMA Welding Arc Temperature</i>		<i>Electrode Manipulation</i>	171
<i>and Heat</i>	150	<i>Practice Welds</i>	173
Types of Currents.....	151	<i>Positioning of the Welder</i>	
Welding Power	152	<i>and the Weld Plate</i>	173
Open Circuit Voltage.....	152	Striking an Arc	174
Operating Voltage.....	153	Tack Welds.....	177
Arc Blow.....	153	Stringer Beads.....	178
Types of Power Sources	154	<i>Square Butt Joint</i>	180
<i>Transformer-Type Welding Machines</i> ...	154	<i>Outside Corner Joint</i>	185
<i>Multiple Coil Welders</i>	155	<i>Lap Joint</i>	188
<i>Movable Coil or Core Welders</i>	156	<i>Tee Joint</i>	193
<i>Inverter Welders</i>	156	Summary.....	197
Generator and Alternator Welders	157	Review Questions.....	199
Converting AC to DC	159	CHAPTER 10 Shielded Metal Arc	
Duty Cycle.....	160	Welding Pipe	200
Welder Accessories.....	160	Objectives.....	200
<i>Welding Cables</i>	160	Key Terms	200
<i>Electrode Holders</i>	161	Introduction	200
<i>Work Clamps</i>	162	Pipe and Tubing	201
Equipment Setup.....	162	<i>Preparation and Fit-Up</i>	202
Summary.....	163	<i>Pipe Welding</i>	205
Review Questions.....	163		

Pipe Welding Passes. 205
Root Weld 205
Hot Pass 206
Filler Pass 206
Cover Pass. 208
1G Horizontal Rolled Pipe Position 208
5G Horizontal Fixed Pipe Position 211
Horizontal Pipe Welds 213
2G Vertical Fixed Pipe Position. 219
Horizontal Welds on Vertical Pipe 219
 Summary 227
 Review Questions. 228

CHAPTER 11 Gas Metal Arc Welding Equipment and Materials 229

Objectives. 229
 Key Terms 229
 Introduction 230
 GMA Welding Equipment 231
 Power Supply 232
 Current Path 232
 Wire Feed Unit. 234
 Feed Roller Tension 236
 Reel Tension 237
 Wire Feed Guide. 237
 Conduit Wire Liner 237
 GMAW Guns 237
 Work Lead 239
 Shielding Gas Flowmeter 240
 Welder Connections 240
 GMAW Shielding Gases 241
 Argon (Ar) 242
 Argon Gas Blends 244
 Helium (He) 244
 Carbon Dioxide (CO₂) 244
 Nitrogen (N) 244

Gas Flow Rate 244
 Shielding Gas Cost 245
 Weld Metal Transfer Methods. 246
 Short-Circuit Transfer—GMAW-S. 246
 Globular Transfer 247
 Axial Spray Transfer 248
 Pulsed-Arc Transfer—GMAW-P 249
 GMAW Electrodes 249
 Electrode Diameters 250
 Electrode Cast and Helix 250
 Electrode Handling 251
 GMAW Electrode Classification. 251
 Carbon Steel and Low-Alloy Wire Electrodes. 251
 ER70S-2 251
 ER70S-3 251
 ER70S-4 252
 ER70S-5 252
 ER70S-6 252
 ER70S-7 252
 ER70S-G. 252
 ER80S-Ni1 252
 ER80S-D2. 252
 Stainless Steel Wire Electrodes. 252
 ER308L and ER308LSi 252
 ER309L and ER309LSi 253
 ER316L and ER316L-Si 253
 Aluminum and Aluminum Alloy Wire Electrodes. 253
 ER1100. 253
 ER4043 253
 ER5356 253
 ER5556 253
 Equipment Setup. 253
 Summary 257
 Review Questions. 257

**CHAPTER 12 Gas Metal Arc
Welding** 259

Objectives	259
Key Terms	259
Introduction	259
Arc Voltage and Amperage	
Characteristics	260
<i>Wire Feed Speed</i>	260
Gun Angle	261
<i>Forehand/Perpendicular/Backhand</i>	
<i>Techniques</i>	262
<i>Electrode Manipulation</i>	263
<i>Practice Welds</i>	263
<i>Electrode Extension</i>	263
Intermittent Butt Welds	266
<i>Lap Joint</i>	271
<i>Outside Corner Joint</i>	274
<i>Tee Joint</i>	278
Summary	289
Review Questions	292

**CHAPTER 13 Flux Cored Arc Welding
Equipment
and Materials** 293

Objectives	293
Key Terms	293
Introduction	293
FCAW Process	294
<i>Equipment</i>	296
Advantages of FCA Welding	298
<i>High Deposition Rate</i>	298
<i>Portability</i>	298
<i>Minimum Electrode Waste</i>	298
<i>Narrow Groove Angle</i>	298
<i>Minimum Precleaning</i>	299
<i>All-Position Welding</i>	299
<i>Flexibility</i>	299
<i>High Quality</i>	299
<i>Excellent Control</i>	299

Limitations of FCA Welding	299
<i>Types of Metals</i>	299
<i>Cost of Equipment</i>	299
<i>Postweld Cleanup</i>	299
<i>Indoor Air Quality</i>	299
FCAW Electrodes	299
<i>Methods of Manufacturing</i>	300
<i>FCAW Electrode Sizes</i>	300
<i>FCAW Electrode Packaging</i>	300
<i>Electrode Cast and Helix</i>	301
FCA Welding Electrode Flux	302
<i>FCA Welding Flux Actions</i>	302
<i>Types of FCAW Fluxes</i>	303
Flux Cored Steel Electrode	
Identification	305
<i>Mild Steel</i>	305
<i>Stainless Steel Electrodes</i>	306
<i>Metal Cored Steel Electrode</i>	
<i>Identification</i>	306
<i>Care of Flux Core Electrodes</i>	306
Shielding Gas	307
Welding Techniques	308
<i>Gun Angle</i>	308
<i>Forehand/Perpendicular/Backhand</i>	
<i>Techniques</i>	309
<i>Travel Speed</i>	311
<i>Mode of Metal Transfer</i>	311
<i>Electrode Extension</i>	312
<i>Porosity</i>	312
Flux Cored	314
Troubleshooting FCA Welding	314
Summary	315
Review Questions	316

**CHAPTER 14 Flux Cored Arc
Welding** 317

Objectives	317
Key Terms	317
Introduction	317

Arc Voltage and Amperage
 Characteristics.....318
 Wire Feed Speed 318
 Electrode Manipulation 319
 Practice Welds 319
 Electrode Extension 320
 Edge Welds and Plug Welds322
 Summary.....337
 Review Questions.....338

**CHAPTER 15 Gas Tungsten Arc
 Welding Equipment
 and Materials..... 339**

Objectives.....339
 Key Terms339
 Introduction339
 GTA Welding Equipment340
 GTA Welding Torches340
 Tungsten Electrodes.....344
 Types of Tungsten Electrodes 344
 Flowmeter346
 Shielding Gas Flow Rate..... 347
 Preflow and Postflow 348
 Shielding Gases.....349
 Argon 349
 Helium 349
 Hydrogen 349
 Nitrogen 350
 Types of Welding Current.....350
 *Direct-Current Electrode
 Negative (DCEN)*..... 350
 *Direct-Current Electrode
 Positive (DCEP)* 350
 *Alternating Current High
 Frequency (ACHF)*..... 351
 Arc Cleaning Action 352
 Hot Start 353
 Remote Controls.....353

Setting Up a GTA Welder353
 Shaping the Tungsten Electrode 353
 Assembling the GTA Welding Station... 356
 Summary358
 Review Questions359

**CHAPTER 16 Gas Tungsten Arc
 Welding..... 360**

Objectives.....360
 Key Terms360
 Introduction360
 Low Carbon and Mild Steels 361
 Stainless Steel 361
 Aluminum362
 Metal Preparation 363
 Setup 363
 Striking an Arc and Pushing a Puddle... 366
 Surfacing Welds 372
 Edge Joints 378
 Tee Joint 381
 Summary384
 Review Questions.....386

**CHAPTER 17 Oxyfuel Welding and
 Cutting Equipment,
 Setup, and Operation 387**

Objectives.....387
 Key Terms387
 Introduction387
 Oxyfuel Equipment388
 Pressure Regulators 388
 Design and Service of Welding
 and Cutting Torches.....393
 Torch Care and Use 394
 Welding and Heating Tips.....395
 Tip Care and Use 396
 Backfires 396
 Flashbacks 396

Reverse Flow Valves 397
Flashback Arrestors 397
Hoses and Fittings 397
Oxyfuel Equipment Setup
and Operation 400
Setting Up an Oxyfuel Torch Set 400
*Turning On and Testing Oxyfuel
Welding Equipment* 402
Types of Flames 404
*Shutting Off and Disassembling
Oxyfuel Welding Equipment* 405
Summary 406
Review Questions 406

**CHAPTER 18 Oxyacetylene
Welding** 407

Objectives 407
Key Terms 407
Introduction 407
Mild Steel Welds 408
Factors Affecting the Weld 408
Characteristics of the Weld 409
Getting Ready to Weld 411
Outside Corner Joint 413
Butt Joint 417
Lap Joint 420
Tee Joint 425
Out-of-Position Welding 428
Vertical Welds 428
Vertical Outside Corner Joint 429
Summary 431
Review Questions 434

**CHAPTER 19 Soldering, Brazing,
and Braze Welding
Processes** 435

Objectives 435
Key Terms 435
Introduction 435

Advantages of Soldering and Brazing 436
Brazing and Braze Welding 437
Physical Properties of the Joint 438
Tensile Strength 438
Shear Strength 438
Ductility 438
Fatigue Resistance 439
Corrosion Resistance 439
Fluxes 439
General 439
Fluxing Action 440
Soldering and Brazing Methods 441
General 441
Torch Soldering and Brazing 442
Furnace Soldering and Brazing 442
Induction Soldering and Brazing 444
Dip Soldering and Brazing 444
Resistance Soldering and Brazing 445
Special Methods 445
Filler Metals 445
General 445
Soldering Alloys 447
Brazing Alloys 448
Joint Design 451
General 451
Summary 454
Review Questions 454

**CHAPTER 20 Soldering
and Brazing** 455

Objectives 455
Key Terms 455
Introduction 455
Brazing 456
*Surfacing, Surface Buildup,
and Filling Holes* 456
Silver Brazing 464
Soldering 474

Summary	483	<i>Plasma Torch</i>	535
Review Questions	486	<i>Cables and Hoses</i>	537
CHAPTER 21 Oxyacetylene Cutting.....	487	<i>Power Requirements</i>	538
Objectives.....	487	<i>Heat Input</i>	539
Key Terms	487	<i>Distortion</i>	539
Introduction	487	<i>Applications</i>	540
<i>Metals Cut by the Oxyfuel Process</i>	488	<i>Gases</i>	544
<i>Eye Protection for Flame Cutting</i>	488	<i>Machine Cutting</i>	544
<i>Cutting Torches</i>	489	<i>Safety</i>	546
<i>Oxyfuel Cutting, Setup,</i> <i>and Operation</i>	495	<i>Manual Cutting</i>	546
<i>Torch Tip Alignment</i>	498	<i>Beveling of a Plate</i>	552
<i>Layout</i>	499	<i>Cutting Round Stock</i>	557
<i>Selecting the Correct Tip</i> <i>and Setting the Pressure</i>	499	<i>Plasma Arc Gouging</i>	561
<i>The Chemistry of a Cut</i>	501	Summary	563
<i>Cutting Applications</i>	501	Review Questions	563
<i>The Physics of a Cut</i>	503	CHAPTER 23 Arc Cutting, Gouging, and Related Cutting Processes.....	565
<i>Slag</i>	506	Objectives.....	565
<i>Plate Cutting</i>	506	Key Terms	565
<i>Cutting Table</i>	507	Introduction	565
<i>Torch Guides</i>	507	<i>Lasers</i>	566
<i>Stopping and Starting Cuts</i>	507	<i>Laser Types</i>	566
<i>Flame Cutting Holes</i>	516	<i>Applications</i>	568
<i>Distortion</i>	521	<i>Laser Beam Cutting</i>	568
<i>Machine Cutting Torch</i>	522	<i>Laser Beam Drilling</i>	569
<i>Irregular Shapes</i>	524	<i>Laser Beam Welding</i>	570
<i>Pipe Cutting</i>	527	<i>Laser Equipment</i>	570
Summary	530	<i>Oxygen Lance Cutting</i>	570
Review Questions	531	<i>Waterjet Cutting</i>	572
CHAPTER 22 Plasma Arc Cutting ...	533	<i>Arc Cutting Electrodes</i>	573
Objectives.....	533	<i>Air Carbon Arc Cutting</i>	574
Key Terms	533	<i>U-Grooves</i>	579
Introduction	533	<i>J-Groove</i>	581
<i>Plasma</i>	534	Summary	584
<i>Arc Plasma</i>	535	Review Questions	585

CHAPTER 24 Other Welding Processes..... 586

Objectives.....586

Key Terms586

Introduction586

Resistance Welding (RW)586

Resistance Spot Welding (RSW) 587

Ultrasonic Welding (USW).....588

Inertia Welding Process.....589

Laser Beam Welding (LBW)589

Advantages and Disadvantages of Laser Welding...... 590

Plasma Arc Welding (PAW) Process590

Stud Welding (SW).....591

Hardfacing.....591

Selection of Hardfacing Metals 592

Hardfacing Welding Processes 592

Quality of Surfacing Deposit 593

Hardfacing Electrodes 593

Thermal Spraying (THSP)594

Thermal Spraying Equipment..... 595

Summary595

Review Questions596

CHAPTER 25 Welding Automation and Robotics 597

Objectives.....597

Key Terms597

Introduction597

Manual Joining Processes 598

Semiautomatic Joining Processes 598

Machine Joining Processes..... 600

Automatic Joining Processes 600

Automated Joining..... 600

Industrial Robots 600

Safety 603

Summary604

Review Questions604

CHAPTER 26 Filler Metal Selection.. 605

Objectives.....605

Key Terms605

Introduction605

Manufacturers' Electrode Information.. 606

Understanding the Electrode Data 606

Data Resulting from Mechanical Tests ... 606

Data Resulting from Chemical Analysis...... 607

SMAW Electrode Operating Information...... 607

Core Wire.....608

Functions of the Flux Covering 608

Filler Metal Selection..... 608

Shielded Metal Arc Welding Electrode Selection 609

AWS Filler Metal Classifications 610

Carbon Steel..... 612

Wire-Type Carbon Steel Filler Metals... 616

Stainless Steel Electrodes..... 618

Nonferrous Electrode..... 621

Aluminum and Aluminum Alloys 621

Aluminum Covered Arc Welding Electrodes 621

Aluminum Bare Welding Rods and Electrodes 621

Special Purpose Filler Metals...... 622

Surface and Buildup Electrode Classification...... 623

Summary623

Review Questions.....624

CHAPTER 27 Welding Metallurgy... 625

Objectives.....625

Key Terms625

Introduction625

Heat, Temperature, and Energy 626

Mechanical Properties of Metal..... 628

<i>Hardness</i>	628
<i>Brittleness</i>	629
<i>Ductility</i>	629
<i>Toughness</i>	629
<i>Strength</i>	629
<i>Other Mechanical Concepts</i>	630
<i>Structure of Matter</i>	630
<i>Crystalline Structures of Metal</i>	631
<i>Phase Diagrams</i>	631
<i>Lead–Tin Phase Diagram</i>	632
<i>Iron–Carbon Phase Diagram</i>	633
<i>Strengthening Mechanisms</i>	634
<i>Mechanical Mixtures of Phases</i>	635
<i>Quench, Temper, and Anneal</i>	636
<i>Carbon–Iron Alloy Reactions</i>	638
<i>Grain Size Control</i>	638
<i>Cold Work</i>	639
Heat Treatments Associated with Welding	639
<i>Preheat</i>	639
<i>Stress Relief, Process Annealing</i>	639
<i>Annealing</i>	640
<i>Normalizing</i>	640
<i>Thermal Effects Caused by Arc Welding</i>	640
<i>Gases in Welding</i>	642
<i>Metallurgical Defects</i>	644
Summary	646
Review Questions	646

CHAPTER 28 Weldability
of Metals **647**

Objectives	647
Key Terms	647
Introduction	647
<i>Steel Classification and Identification</i>	649
<i>Carbon and Alloy Steels</i>	649
<i>Stainless Steels</i>	652

<i>Cast Iron</i>	653
<i>Practice Welding Cast Iron</i>	655
<i>Welding without Preheating or Postheating</i>	656
<i>Aluminum Weldability</i>	659
<i>Repair Welding</i>	659
Summary	663
Review Questions	663

CHAPTER 29 Welder
Certification **665**

Objectives	665
Key Terms	665
Introduction	665
<i>Qualified and Certified Welders</i>	666
<i>Welder Performance Qualification</i>	666
<i>Welder Certification</i>	667
<i>AWS Entry-Level Welder Qualification and Welder Certification</i>	667
<i>Welder Qualification and Certification Test Instructions for Practices</i>	667
<i>Restarting a Weld Bead</i>	669
Summary	699
Review Questions	700

CHAPTER 30 Testing and Inspecting
Welds **701**

Objectives	701
Key Terms	701
Introduction	701
<i>Quality Control (QC)</i>	702
<i>Discontinuities and Defects</i>	702
<i>Porosity</i>	702
<i>Inclusions</i>	704
<i>Inadequate Joint Penetration</i>	704
<i>Incomplete Fusion</i>	705
<i>Arc Strikes</i>	706
<i>Overlap</i>	707

Undercut	707	Free-Bend Test	715
Crater Cracks	707	Alternate Bend	716
Underfill	708	Fillet Weld Break Test	716
Weld Problems Caused by Plate Problems	708	Impact Testing	718
Lamellar Tears	709	Nondestructive Testing (NDT)	718
Lamination	709	Summary	723
Delamination	709	Review Questions	723
Destructive Testing (DT)	710	Glossary	724
Shearing Strength of Welds	711	Appendix	784
Welded Butt Joints	713	Index	800
Nick-Break Test	713		
Guided-Bend Test	713		